

Tech Notes

Unserviceable US Army Surveying Instrument

Not Mission Capable. Do NOT deploy on
Missions requiring this survey instrument

Subject

LIN: S03726 NSN: 6675-01-372-0047

Nomenclature: AISI (Automated Integrated Surveying Instrument); Electronic DIST-ANGLE

This Surveying Instrument is **non-supportable and unserviceable** due to its age and obsolescence of outdated electronic components needed to repair it.

End of CY20: All remaining AISI's fielded at Army Engineer Units will cease functioning and cannot be repaired.

Do not take the AISI's on missions requiring land surveying to be conducted by Army Engineers 12T's.

POC for AISI replacement with same Fit/Form/Function listed below.



USARMY_surveygear@trimble.com